Software Name	File Type	Supported Equipment	Cost	Comments
383 PCW	**NA**	383 OTDR	Free	Used to view/print traces from 383 OTDR
OTDRCOPY.exe	**NA**	340 OTDR	Free	Allows you to download data from a 340 OTDR via the serial transfer port. This is very slow, thus we would suggust using the floppy drive transfer method.
LinkLoss	**NA**	OTS-100 OTS-200 OTS-300	Free	Allows you to transfer data via the serial port from the OTS series tester and view/print data on the computer.
LinkLoss 2	**NA**	OTS-100 OTS-200 OTS-300	No longer Availble for Purchase	Allows you to merge two data files (odd and even number fibers), or merge bidirectional loss data into one file.
TraceView	**.trl** **.sor**	OTDR-340 500 Multitester	Free	Allows you to view/print files from the OTDR-340 and Multitester 500. Transfer of the data from unit to computer can be done via the floppy drive (400 or 500) or burned to CD (500).
Softview	**.trl** **.sor**	OTDR-340 500 Multitester	No longer Availble for Purchase	This is an add-on software to Traveview that allows some batch processing (add title to all traces, move markers on all traces, etc). Sold with all 500-Multitester deluxe kits.

OTSVIEW **Optivisor 400 Aplication** **OTS Report Processor** **Data Transfer**	**.olts** **.olts2** **.hhdt**	OTS-400 Handhelds OTS-500 Handhelds Optivisor 400 OTDR	Free	**Comes with the following applications:**
				 * **Data Transfer** - Used to transfer data from Optivisor 400 OTDR, OTS-400, and OTS-500.
				 * **OTS View** - viewer package which contains the following
				   - Optivisor 400 viewer - Allows viewing of traces from OV-1000 and Optivisor 400 OTDRs
				   - Optivisor 400 bidirectional viewer - Allows you to merge bidirectional data for SM fiber only.
				   - OTS Report Prosser - Allows viewing of loss values from the OTS units (must install Update service packs)
				 * **OptiVisor 400 Application** - OTDR application upgrade (not computer software, installation not suggested for new unit)

OV-1000 **Compact Modular Platform** **Software Installation**	**.trc** **.sor**	OV-1000	Free	**Comes with the following Menu from CD being inserted:**
				 * **Release Note** - Print out and read before installing any software
				 * **Start Installation**
				   - Handheld Instrument - Unit application upgrade (not computer software, installation not suggested for new unit)
				 * **Viewers and Utiltities**
				   - VNC client - used to output the OV-1000 screen to a computer monitor (not suggested)
				   - Microsoft ActiveSync 2.0 - Allows data transfer via USB from OV-1000 to computer
				   - OTS View - viewer package which contains the following
				     + Optivisor 400 viewer - Allows viewing of traces from OV-1000 and Optivisor 400 OTDRs
				     + Optivisor 400 bidirectional viewer - Allows you to merge bidirectional data for SM fiber only.
				     + OTS Report Prosser - Allows viewing of loss values from the OTS units (not really required for OV-1000 unit)
				   - Handheld Data Transfer - Do not install, not need for OV-1000 (used only with OTS units)
				   - Adobe Acrobat Reader 7.0 - Install if do not already have on your computer in order to view user manual
				   - Compact PB Report Generator - Need to view results from Gigabit Ethernet testing module (if purchased)
				 * **User Guide** - this is the manual
				 * **Contact Corning** - information about phone number, website, etc
				 * **Explore CD** - allows you to actually view the files on the CD

OTS Batch		OV-1000	Purchase	This is an add on software (standard with 1000DK kits) that allows some batch processing. For example you can modify the header information from multiple traces in a batch process or move all the markers in multiple traces to the same location.